

Food Premises Inspection Summary Report

Name of Premise: Oromocto Public Hospital Address: 103 Winnebago St Oromocto NB E2V 1C6 Water Supply: Municipal	Licence #: 03-00160 Type: Class/Classe 4 Category: Follow-up Date of Inspection: December 14, 2023
-----------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------

MI - Minor infraction; MA - Major infraction; CR - Critical infraction; CDI - Corrected During Inspection; N/A - Not Applicable

OBSERVATIONS AND CORRECTIVE ACTIONS

Item	MI /MA/ CR	Remarks	Date for Correction
11.2	MI	<p>Outstanding Infraction: If the premises is on private on-site sewage disposal system a grease trap must be present. These chambers must be sized and maintained in accordance with the manufacturer's instructions.</p> <p>Comment: This issue was previously noted on December 1 2023. Food handler indicated that the grease trap was inspected by maintenance and the part is on order.</p>	
10.2	MI	<p>Outstanding Infraction: Walls shall be of sound construction and in good repair.</p> <p>Comment: This issue was previously noted on March 9 and December 1 2023. Please repair and apply a finish on walls especially for high traffic areas so they can be easily cleaned.</p>	

CLOSING COMMENTS

All outstanding infractions are to be corrected at the next routine inspection.

Rating colour: Green